


OPTIONAL PRESSURE FEEDER APV-1000 / APV-2000



NOTE: Do not pressurise the tank above 7 bar (100psi). Most samples only require approximately 1 bar (15psi) to adequately feed the homogeniser.

WARNING: Depressurize pressure feeder tank to atmospheric pressure before opening lid or detaching from homogenizers.
Ignoring this warning may cause serious injury.

Item	Description
7	O-Ring P/N 80110040 (EPDM)
8	Hex Socket Bolt (2) P/N K001018
152	Inlet Connection P/N 34230020 1"
153	Tank Clamp Gasket P/N 80210032 1" (PTFE)
154	Tank Clamp P/N P720525
155	Pressure Feeder Tank P/N 24730000
156	Piston P/N 122010
157	Cap Gasket P/N 84130038 4" (EPDM)
158	Cap Clamp P/N P716976 4"
159	Cap P/N 84130031
160	Pressure Relief Valve P/N 905197
161	1/8 NPT Provision For Male Quick Connect Fitting
162	Inlet Connection P/N 34230027